


SAFETY – CERTIFICATE

It is certify that Kendriya Vidyalaya No.2 Army Jodhpur Building, Principal Residence (D-1) Staff quarter Block of Four (B-1 TO B-4), Staff quarter Block four (C-1 TO C-4) have been inspected visually and No cracks/sinking in floor seen. Building is structurally safe as on 31.07.2021.



(12/12/21)

JR(eiv)